

	<p>REPUBLIC OF NAMIBIA NAMIBIA CIVIL AVIATION AUTHORITY AIRAC AIP SUPPLEMENT</p>	Executive Director Namibia Civil Aviation Authority Private Bag 12003 Ausspannplatz WINDHOEK
Tel: +264 61 702082/2203 Fax: +264 61 702088 e-mail: aip@ncaa.na		<p>AIRAC AIP SUP S02/2022 19 May 2022</p>

HOSEA KUTAKO(FYWH) INTERNATIONAL AIRPORT APRON MARKING

Effective date: 14 July 2022

Validity: The SUPPLEMENT remains in force until cancelled or replaced.

This SUP is replacing SUP S01/2022.

1. APRON MARKINGS

- 1.1 Airport Apron lead in lines are not commensurate with aircraft operations.
- 1.2 There are no aircraft stand markings on FYWH apron.
- 1.3 Pilots are to follow aircraft marshaller instructions.

2. PRE FLIGHT-ALTIMETER CHECK LOCATION

- 2.1 NAC has currently not established and thus not published the preflight altimeter check locations.
- 2.2 The pre-flight altimeter checks are currently conducted on any position on the Apron. Pilots obtain the QNH from ATC, which is obtained from the Pressure Sensor of Meteorological Services.

3. PAVEMENT STRENGTH

Area	(Pavement Classification Number) PCN
Main runway	76/F/B/W/T
Secondary runway	100/F/B/W/T

Parallel taxiway	65/F/B/W/T
Intersection B/C/D/E	65/F/B/W/T
Asphalt Apron	100/F/B/W/T
Concrete Apron	65/R/B/W/T

4. AERODROME OPERATION HOURS (UTC)

Aerodrome operation hours: 0300 -1930 daily

ARFF: cat 9, available 24/7

For after hour operations, pre-approval required from Senior Airport Manager.

5. AERODROME REFERENCE TEMPERATURE

The Aerodrome Reference Temperature at HKIA is 35 Degrees Celsius.

6. PRECISION APPROACH PATH INDICATORS (PAPI)

The Precision Approach Path Indicators PAPI for Runway 34 are Unserviceable.